National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 09/20/2002

DEN02LA041

File No. 12297	04/28/2002	Greeley, CO	Aircraft Reg No. N4730Q		Time (Local): 12:00 MDT		
Engine Make/Mo Aircraft Dama Number of Engin Operating Certificate Type of Flight Operati	(s): None		Crew Pass	Fatal 0 0	Serious 0 0	Minor/None 2 0	
Last Depart. Point: Destination: Airport Proximity: Airport Name: Runway Identification: Runway Length/Width (Ft): Runway Surface: Runway Surface Condition: Same as Accident/Incident Location Coral Flight On Airport Greeley-Weld County Airport 09 6210 / 100 Asphalt Dry		Condition of Light: Day Weather Info Src: Weather Observation Facility Basic Weather: Visual Conditions Lowest Ceiling: None Visibility: 10.00 SM Wind Dir/Speed: 010 / 004 Kts Temperature (°C): 18 Precip/Obscuration: None / None					
Certificate(s)/Rating(s))/Rating(s) structor; Commercial; Multi-engine Land; Single-engine Land Ratings		Т	Flight Time (Hours) Total All Aircraft: 19100 Last 90 Days: 176 Total Make/Model: 12000 Total Instrument Time: 806			

The pilot receiving instruction said, "Late in landing roll ... at approximately 25-30 mph brakes were applied and left brake failed due to ruptured brake line. Airplane veered right and ground-looped causing left wing tip and left elevator to contact runway." An examination of the airplane's left main landing gear showed that the left brake line was cracked, flattened, and leaking brake fluid.

Brief of Accident (Continued)

DEN02LA041

File No. 12297 04/28/2002 Greeley, CO Aircraft Reg No. N4730Q Time (Local): 12:00 MDT

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. BRAKES(NORMAL) - ACTIVATED - DUAL STUDENT

2. (F) LANDING GEAR, NORMAL BRAKE SYSTEM - FAILURE, PARTIAL

3. (C) GROUND LOOP/SWERVE - ENCOUNTERED

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows. the inadvertent ground loop during landing roll. A contributing factor was the partial brake system failure.